


FIG.1



2/14

FIG.2






FIG.3



4/14

FIG.4



5/14

FIG.5






FIG.6



6/14








FIG.8



9/14

FIG.9

WIRELESS
TERMINAL 11




10/14

FIG.10

	NACK/ACK OF THE PREVIOUS UPLINK CONTROL SIGNAL	INCORRECT RECEPTION OF THE UPLINK CONTROL SIGNAL
WIRELESS TERMINAL 10	NACK	YES
WIRELESS TERMINAL 11	ACK	NO


11/14

FIG.11



12/14

FIG.12



13/14

FIG.13





FIG.14



14/14

FIG.15

